National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 04/01/2003

DEN03l	_A003
--------	-------

File No. 12771	10/06/2002	10/06/2002 Broomfield, CO		N65312	Time (Local): 10:00 MDT	
Engine Make/ Aircraft Da Number of Ei Operating Certific Type of Flight Ope	•		Crew Pass	Fatal 0 0	Serious 0 0	Minor/None 1 1
Desti Airport Pro Airport Runway Identifi Runway Length/Wid Runway S	Last Depart. Point: Destination: Airport Proximity: Airport Name: Runway Identification: Runway Length/Width (Ft): Runway Surface: Runway Surface Condition: Lenglewood, CO Same as Accident/Incident Location On Airport Jefferson County Unk/Nr Unk/Nr Unk/Nr Unknown Unknown		Condition of Light: Day Weather Info Src: Weather Observation Facility Basic Weather: Visual Conditions Lowest Ceiling: 12000 Ft. AGL, Broken Visibility: 50.00 SM Wind Dir/Speed: 130 / 008 Kts Temperature (°C): 10 Precip/Obscuration: None / None			
Pilot-in-Command Certificate(s)/Rating(s) Private; Single-engine Land Instrument Ratings None	Age: 53		Т	Total . Las Total Ma	me (Hours) All Aircraft: 1 st 90 Days: U ake/Model: 1 ment Time: U	lnk/Nr 68

The pilot was unfamiliar with the airport and asked ground control for directions to transient parking. She was directed to an area southeast of the control tower, but the ramp was full. The pilot said her husband was talking and directing her. She asked him to be quiet but he kept talking. During the "spirited discussion," the pilot lost focus and concentration, and misjudged her relative position to a steel light post near a building. The pilot also said the sun was in her eyes. The airplane's left wing struck a pole, damaging the leading edge just outboard of the lift strut, and crushing the aft spar.

Brief of Accident (Continued)

DEN03LA003

File No. 12771 10/06/2002 Broomfield, CO Aircraft Reg No. N65312 Time (Local): 10:00 MDT

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: TAXI

Findings

1. (C) CLEARANCE - MISJUDGED - PILOT IN COMMAND

2. (F) DIVERTED ATTENTION - PILOT IN COMMAND

3. (F) LIGHT CONDITION - SUNGLARE

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows. the pilot misjudging the clearance between the airplane and a fixed object during taxi. Contributing factors were the pilot's attention being diverted and sunglare.